

DEPARTMENT OF PUBLIC WORKS

No: Sakaha/KahuV-4/Ke.Im/K. Confirmation Letter/2023-24/154

Date: 30/05/2023

To,
The Secretary,
South Asian Central Academy,
(South Asian Trust),
No. 109/2 & 107/3, Andrahalli,
Vishwaneedam Post,
Bangalore – 560 091.

Respected Sir/Madam.

Subject: Regarding issuance of safety certificate of college building.

Reference: 1. Their appeal letter dated: 03.05.2023

2. Government of Karnataka Additional Secretary, Public Works
Department circular letter no: LoE 59 BED 2019 Bangalore
Dated: 06.05.2022.

In relation to the above, South Asian Central Academy run on behalf of South Asian Trust (R), No. 109/2 & 107/3, Andrahalli, Vishwaneedam Post, Bangalore – 560 091. In the letter referred to (1) you have requested to issue a safety certificate for the building.

Accordingly, South Asian Central Academy, run by South Asian Trust (R), No. 109/2 & 107/3, Andrahalli, Vishwaneedam Post, Bangalore – 560 091, the concerned Engineer and Secretary of the organization Mr. Yatish Patel, inspected the interior and exterior of the school building on 25/05/2023. The said building having ground plus two floors, the ground and first floor were constructed in 2006 and currently the third floor is being constructed. The building is made of Vertified Tiles, Aluminum windows and iron doors are fitted. The ground and first floor of the said building constructed was found with 07 rooms each and 10 rooms with toilets in the second floor.

Building related concrete grade, steel, cement, sand etc. for construction work in the Government circular of reference (2) due to non-availability of test reports of fitting materials as indicated two types of Non Destructive tests are carried out.



For South Asian Central Academy

y. Rajapriya
Manager

For South Asian Central Academy

Ramya
Principal

Continued. From Bangalore University Department of Civil Engineering (U.V.C.E) Form for certificate for Structural Design Sufficiency Report (Annex -C Clause 12.2.8), Ultrasonic pulse velocity test Report and Rebound Hammer Test by U.V.C.E. Bangalore University, Civil Engg Department Professor Dr. N. Jayaramappa, B.E (Civil), ME(Str), Ph.D. Tested by The reports confirm that they have been constructed as per the National Building Code of India.


You have submitted the following necessary documents.

1. Ultrasonic Pulse Velocity Test Report
2. Rebound Hammer Test result.

Order No. (2) of the Government Circular of reference (2) one in an urban area as indicated in School/College Rs. 5,000.00 as fee by the said institution Challan Reference No: CR0523005900530229 dtd. As on 30.05.2023 Rs. 5,000.00 have been paid.

All the floors and important parts of the building of the said institution were inspected. The first floor ceiling is very plastered. After completion of work on second floor, then the first floor classrooms had little moisture because of second floor construction. It is the responsibility of the building maintainer to take immediate action to correct the moisture. It is the responsibility of the institution and it is subject to revocation of this certificate at any time.

If any changes or additions are made in the building in the near future, the certificate will get automatically cancelled. Hence, the South Asian Trust (R), No. 109/2 & 107/3, Andrahalli, Vishwanedam Post, Bangalore - 560 091 has been issued a Building Safety Certificate. The said Building Safety Certificate for the school building here to be used for educational purpose only.



For South Asian Central Academy

Sajapriya
Manager

17 APR 2024

ATTESTED BY ME

LB
L.B. ANASUYAMMA, B.A.LL.B.
ADVOCATE & NOTARY PUBLIC
GOVT. OF INDIA
Old No.224/4, New No B-48/5
Bahubali Nagar, Jaiahalli
Bengaluru - 560 013

Yours faithfully,

Assistant Executive Engineer
No.4, Buildings Subdivision
Department of Public Works

For South Asian Central Academy

Ramya
Principal

Translated from... *Kannada* ...to... *English* ...

Rm